

ALLEGIANCE

TRUCKS™

AT NORTHERN NEW JERSEY, LLC
 ALLEGIANCE TRUCKS LINDEN
 1410 East Linden Ave.
 LINDEN, NJ 07036
 P:(908) 862-8181
 F:(908) 862-7621



BILL TO
 PASSAIC COUNTY ROAD DEPT - 17217
 1310 ROUTE 23 NORTH
 WAYNE, NJ 07470
 P: (973) 881-4522

DELIVER TO
 PASSAIC COUNTY ROAD DEPT - 17217
 1310 RT. 23N
 WAYNE NJ 07470
 P: (973) 881-4522

X403256805-01
 X403256805-01
 X403256805-01

PARTS INVOICE: X403256805:01
 ESTIMATE: E403071522:01

| DATE SHIPPED | SHIP VIA | DATE INVOICE | SALESPERSON | UNIT ID | VIN | SALE TYPE | TERMS | EMPID | CUS REFERENCE |
|--------------|----------|---------------------|-------------|---------|-----|-----------|-------|-------|---------------|
| 10/23/2025 | DELIVERY | 10/24/2025 11:47 am | Michael P | | | PRET | CB | | 25-04541 |


| QTY SHP | QTY B/D | ITEM | DESCRIPTION | BIN | LIST PRICE | UNIT PRICE | EXTD PRICE |
|---------|---------|----------------------|--------------------------------|--------|------------|------------|------------|
| | | UNIT R78 | | | | | |
| 2 | | 403N/3621545C1 | CLAMP, EXHAUST PIPE, 5.0 | 006B02 | 73.38 | 48.29 | 96.58 |
| 2 | | 403N/3998694C1 | STRAP, MUFFLER | 006B05 | 48.26 | 40.38 | 80.76 |
| 2 | | 403C/4328745 | CLAMP,T BOLT | 010B01 | 102.73 | 93.48 | 186.96 |
| 1 | | 403C/2866337 | GASKET,AFM DEVICE | 010D02 | 20.08 | 18.27 | 18.27 |
| 1 | | 403C/4384811 | SENSOR,TEMPERATURE | 010D03 | 288.37 | 262.42 | 262.42 |
| 1 | | 403C/4307496 | SENSOR,AMMONIA | 011E03 | 1,056.98 | 961.86 | 961.86 |
| 1 | | 403N/2510789C91 | WELDMENT, CONVERTER, SCR, AFTE | NOLOC | 11,806.60 | 8,946.02 | 8,946.02 |
| 1 | | 403N/2510789C91-CORE | WELDMENT, CONVERTER, SCR, AFTE | | | 762.00 | 762.00 |
| 1 | | 403C/4326872RX | 4326872D SENSOR,NITROGEN OXIDE | W01A00 | 769.63 | 699.87 | 699.87 |
| 1 | | 403C/4326872RX-CORE | 4326872D SENSOR,NITROGEN OXIDE | | | 265.63 | 265.63 |

THANK YOU-WE APPRECIATE YOUR BUSINESS

DISCLAIMER:

The seller hereby expressly disclaims all warranties, either express or implied, including all implied warranties of merchantability or fitness for the particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sales of these parts. Customer agrees to pay all costs of collections, including attorney fees, if amount due on invoice become delinquent. Due and payable by 10th of following month, subject to late charges of 1.5% per month. No refund without this invoice. 25% handling charge on parts returned within 10 days. Special order and electrical parts not returnable. No parts returnable after 10 days. All cores must be returned within 30 days or no returns will be accepted.

| | |
|--------------|---------------------|
| SUB-TOTAL | \$ 12,280.37 |
| PREPAY | \$ 0.00 |
| TAX | \$ 0.00 |
| SHIPPING | \$ 0.00 |
| TOTAL | \$ 12,280.37 |



Please Remit Payment to:
 AT NORTHERN NEW JERSEY, LLC
 CORPORATE BILLING LLC
 DEPT 100 PO BOX 830604
 BIRMINGHAM, AL 35283

SIGNATURE X

R05/58373

AT NORTHERN NEW JERSEY, LLC
 ALLEGIANCE TRUCKS LINDEN
 1410 East Linden Ave.
 LINDEN, NJ 07036
 P: (908) 862-8181
 F: (908) 862-7621

SERVICE INVOICE: R403034352:01

Tag Number: 5626
 License Plate Number:

DEPT - 17217

DELIVER TO
 PASSAIC COUNTY ROAD DEPT - 17217
 1310 RT. 23N
 WAYNE NJ 07470
 P: (973) 881-4522

| SALES TYPE | ADVISOR | TERMS | EMP OVERRIDE | CUS REFERENCE | |
|-------------------|---------------|--------------|--------------|--------------------|----------|
| SRET | MICHAEL M | CB | | 24-00091 | |
| VIN | Fleet Unit ID | ENGINE HOURS | IN SERVICE | Component Serial # | ODOMETER |
| 1HTWDAZRDXH404200 | R-65 | 2,150 | 1/1/2013 | | 21036 |

Sold Operations

DIAGNOSTICS 4 HOURS

CLIENT REPORTS CHECK ENGINE LIGHT, RUNS ROUGH. CHECK AND ADVISE
 CACET CROSSOVER. WASTEGATE. CAC PIPING, BELT/TENSIONER
 CORRECTED. TRUCK AND BROUGHT INTO SHOP. CONNECTED TO OUR LAPTOP DIAGNOSTIC TOOL. TECH NOTED
 WITH THE TRUCK RUNNING A BOOST LEAK IS HEARD. OIL SHOWING UP AT TURBOS AND CAC HOSES,
 ASSEMBLY DUE TO THE BOOST LEAKS.. RAN ENGINE AT HIGH RPM. NOTICED OIL BUBBLING AT REAR
 CROSSOVER PIPE TO INTAKE SEAL. HOSE FOR WASTE GATE CONTROL BROKEN AND OFF OF THE ADAPTER
 OF THE INTAKE. IT WILL NEED A FAN BELT AND TENSIONER. REMOVE RIGHT SIDE FENDER FOR ACCESS TO
 THE CAC PIPING. REMOVE AT THE TURBO. TURBO ALSO SHOWING OIL BUT THAT COULD BE DUE TO THE
 BOOST LEAK AS WELL. PRESSURIZE CAC PIPING TO THE INTAKE. LEAKING EXCESSIVELY AT THE CAC INLET
 CLAMP ON THE PIPE. REPLACED CLAMP. LEAK ONLY SLOWED A LITTLE. WILL NEED TO REPLACE THE PIPE
 HOSE TO ANY MORE TESTING. ALSO SAW THE SPINNER FILTER NEEDS THE INSULATORS TO MOUNT IT. IT
 WAS RECENTLY REPLACED. RADIATOR STAY ROD ON THE RIGHT SIDE WILL NEED NEW INSULATORS,
 LEAVES AND MOUNTING BOLTS. BOTH REAR SPRINGS HAVE BROKEN LEAVES IN THEM. REASSEMBLE FOR
 ROADWAY A RELATIVE COMPRESSION TEST. CYLINDERS APPEAR TO BE WITHING SPECS AT THIS TIME.
 NO OIL BLOWBY PRESENT. CAME UP WITH A PARTS LIST ON TEH ENGINE TO KEEP GOING ON TESTING. CAC
 HOSES LEAKING EXCESSIVELY AS WELL AS THE SEAL IN THE REAR OF THE INTAKE. MORE TESTING WILL
 BE DONE ONCE THE PARTS ARE REPLACED. WILL NEED ADDITIONAL TIME FOR THIS. MAY NEED
 MORE PARTS UPON DISASSEMBLY AND FURTHER TESTING. MUST REPLACE THE EGR CROSSOVER PIPE,
 WASTEGATE HOSE. CAC PIPE AND CLAMPS, BELT AND TENSIONER. WE WILL RETEST AFTER. ANY
 ADDITIONAL REPAIRS WILL BE ADDED TO THE ORIGINAL ESTIMATE.

| QTY | DESCRIPTION | LIST | UNIT PRICE | EXTD PRICE |
|-----|----------------------|-------|------------|------------|
| 1 | DIAGNOSTICS 4 HOURS | | | 640.00 |
| 1 | COMPUTER HOOK UP FEE | | 85.00 | 85.00 |
| 1 | CLAMP, HOSE | 87.45 | 56.90 | 56.90 |

Prepay: 0 Parts: \$56.90 Labor: \$640.00 Misc: \$85.00 Sublet: \$0.00 5781.90

STANCE

Sold Operations (Cont.)

JOE...
 CUR...
 CAP...
 COP...
 REPAIR...
 SPRINGS, BODY MARKER LIGHTS, BRAKE LIGHTS
 BOTH SIDES REAR LEAF SPRINGS WITH ALL NEW HARDWARE. REPAIRED BODY LIGHTS & BRAKE
 ASSEMBLED ALL & RECHECK OPERATION, OK.

| DESCRIPTION | LIST | UNIT PRICE | EXTD PRICE |
|-------------------------------------|----------|------------|------------|
| REAR LEAF SPRING, SUSPENSION, REAR, | 1,418.74 | 981.67 | 1,963.34 |
| Front Suspension, Plate, Spr | 190.37 | 160.25 | 320.50 |
| REAR MARKER LIGHT/ BRAKE LIGHT | | | 640.00 |
| REAR REAR LEAF SPRINGS | | | 1,280.00 |
| Washer, 5/8-in Cad Pt | 15.50 | 10.20 | 81.60 |
| LOCK WASHER, 0.938 X 1.75 X 0.2 | 5.48 | 3.39 | 27.12 |
| Front Suspension, Plate, Spr | 190.37 | 160.25 | 320.50 |
| REAR LEAF SPRING, SUSPENSION, REAR | 103.03 | 84.56 | 84.56 |
| REAR LEAF SPRING 4 DEGR | 59.85 | 51.12 | 51.12 |
| SHOCK BOUND | 33.22 | 27.48 | 109.92 |
| REAR LEAF SPRING U-BOLT, SUSPENSIO | 81.91 | 67.22 | 134.44 |
| U-BOLT, SPRING, SUSPENSION, 7/ | 52.23 | 44.60 | 178.40 |
| WASHER, W/SHOCK | 87.45 | 56.90 | 227.60 |
| WASHER, 1/2 X 50 MM | 7.69 | 5.78 | 23.12 |
| WASHER, 1/2 X M16 PRVTRQ | 7.64 | 4.97 | 19.88 |
| WASHER, Led S/T, Super 44, Led | 27.39 | 21.78 | 21.78 |
| WASHER, Lamp, For 4 In, Black | 4.58 | 2.88 | 5.76 |
| Lamp Kit, Led Clearance/marker | 15.12 | 12.02 | 12.02 |
| LED BACK-UP LAMP 6 DI | 133.00 | 99.71 | 99.71 |

Prepay: 0 Parts: \$3,681.37 Labor: \$1,920.00 Misc: \$0.00 Sublet: \$0.00 \$5,601.37

JOE...
 CUR...
 CAP...
 COP...
 REPAIR...
 REAR DIFF HOUSING
 REAR DIFF HOUSING SERVICE FOUND THAT THE REAR DIFFERENTIAL HOUSING IS EXCESSIVELY CORRODED THIS
 CONDITION IS CAUSING THE REAR TO SHIFT BACK & FORTH IN THE HOUSING. MUST REPLACE THE REAR
 DIFFERENTIAL HOUSING. WILL RE-TEST. ANY SUPPLEMENTAL REPAIRS WILL BE ADDED TO THE ORIGINAL
 ESTIMATE.

REPLACED HOUSING

| DESCRIPTION | LIST | UNIT PRICE | EXTD PRICE |
|--------------------------------|-----------|------------|------------|
| R&R REAR HOUSING (SPLIT) | | | 1,368.00 |
| HOUSING, REAR AXLE | 13,066.94 | 6,694.03 | 6,694.03 |
| GASKET, AXLE SHAFT, REAR | 14.29 | 9.50 | 9.50 |
| SEAL, WHEEL BEARING, OIL, REAR | 55.17 | 36.28 | 72.56 |
| REAR REAR HOUSING (SPLIT) | | | 1,368.00 |
| ELECTRIC CLEANER | 21.00 | 17.00 | 17.00 |
| Washer, Black Hex, 5/8-18 Thr | 5.80 | 3.60 | 3.60 |
| WASHER, BOLT CARRIER TO HOUSIN | 6.29 | 2.96 | 2.96 |
| Screw, 5/8-18 X 1.75 | 6.73 | 5.39 | 5.39 |
| AXLE END LOCK WASHER | 6.22 | 5.96 | 11.92 |

Prepay: 0 Parts: \$6,816.96 Labor: \$2,736.00 Misc: \$0.00 Sublet: \$0.00 \$9,552.96

Prepay: 0 Parts: \$14,094.04 Labor: \$6,857.60 Misc: \$85.00 Sublet: \$0.00 \$21,036.64

